

U. S. Department of Agriculture
FOREST SERVICE

K-1-16

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4 th Mer.

Special Meander Corner common to Sections 15

Corner consists of a 2" Scribed Post and 5" Iron pipe (not) in place

State condition Good

Dimensions above ground Post 24" Pipe 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

M.C. S. 15		M.C. S. 15	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C. S. 12

M.C. S. 12

--

--

B.T.

B.T.

--

--

Species W. Pine W. Pine

Diameter 14" 20"

Bearing S78°E N20°E

Distance 38 Lks 50 Lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by County Surveyor.

Arthur Johnson
(Signature)

Squad Foreman
(Title)

11/23/39
(Date)

R-6-16

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of.

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

R.

T.

U. S. Department of Agriculture
FOREST SERVICE

K-L-15

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

Special Meander Corner common to Sections

and 15
Corner consists of a 2nd class ~~post~~ ^{scribed post} (Rotted off) ~~560~~ in place

State condition good

Dimensions above ground Post 24" pipe 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

M.C.	M.C.		
S. 15	S. 15		
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C.	M.C.		
S. 12	S. 12		
B.T.	B.T.		

Species W. Pine W. Pine

Diameter 14" 20"

Bearing S75°E N20°E

Distance 38 lks 50 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by County Surveyor.

Arthur Jones
(Signature)

Squad Foreman
(Title)

11/23/39
(Date)

K-L-16

This corner was checked 7/15/52
by Orville E. Lind and Virgil D. Smith.
The corner poster was placed at
location. The 1st W.P. is 18" and the
2nd W.P. is 24"

Corner again.

Give any further facts which will aid in finding this

chains distant.

3

from which this Corner bears

N10E

side of


tree

tree 7" inches diameter, on the

SW

Metal Location Poster is on a

Red Oak



(Make sketch of topography near Corner)

T. 57N. R. 26W. 975 Mer.