

## U. S. Department of Agriculture

## FOREST SERVICE

N4-3

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.Meander Corner common to Sections, 18, and 19Corner consists of a F.S. APPROX. POST (not) in placeState condition GoodDimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Grown</u> <u>over</u>	<u>M.C.</u> <u>S. 1/8</u>		
	<u>B.T.</u>		

Species Ash AshDiameter 6" 8"Bearing 276°W N26°WDistance 39 lks 71 lks.Do you believe this to be a genuine Land Office Corner? NBIf not, why? Records show it was set byCounty SurveyorArthur J. Johnson

(Signature)

2/8/90


(Date)

Special Foreman

(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 52N R. 26W Mer. 97A