

U. S. Department of Agriculture  
FOREST SERVICE

27  
4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 27 W 4th p. Mer.

center 1/4 Corner common to Sections  
2, and

Corner consists of a Aspen post (not) in place  
State condition Good

Dimensions above ground 3 x 3 x 36 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Yellow post		C 1/4 S 2 T 57 N R 27 W	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species None  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Do you believe this to be a genuine Land Office Corner? NO  
If not, why? Set by me.

Seth W. Peterson  
(Signature)

2/24/38  
(Date)

Jr. Asst. to Tech.  
(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a No poster set.

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

Corner is about 6 Ch. from NE edge of large open swamp. No trees near on which to place poster. Poster nailed to corner post to aid identification in the future.

6-19