

U. S. Department of Agriculture
FOREST SERVICE

B-3
19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 27 W 4th P. Mer.



NC (#5) 1/16 Corner common to Sections
.....,, 2, and

Corner consists of a Aspen post (not) in place
State condition good

Dimensions above ground 3 x 3 x 30 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No


If not, why? set by me.

Seth W. Peterson
(Signature)

2/24/38
(Date)

Jr. Asst. to Tech.
(Title)

(Make sketch of topography near Corner)



T. 57 N. R. 27 W. 4th P. Mer.

Metal Location Poster is on a Palm of Gilead tree 10 inches diameter, on the South

side of clearing

from which this Corner bears N 30° E (Va. 4° E)

2.66 chains distant.

Give any further facts which will aid in finding this Corner again.

B-19