

U. S. Department of Agriculture

FOREST SERVICE

C-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 27 W 4th p Mer.

E.C. 1/16 (#8) Corner common to fractions

and 2

Corner consists of a cedar post (not) in place



State condition Good

Dimensions above ground 4 x 4 x 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species None

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? Located by me by proportional measurement.

Seth W. Peterson (Signature)

3/2/38 (Date)

Jr. Asst. to Tech. (Title)

C-20

just E of intersection of Truck
Trails 570 and 591

Corner again.

Give any further facts which will aid in finding this


0.36 chains distant.

from which this Corner bears S 10° W

side of R.O.W. MP 570

tree 10 inches diameter, on the North

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 57 N R. 27 W 4th P Mer.