

U. S. Department of Agriculture
FOREST SERVICE


C-25

~~Chippewa~~ NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. ~~57 N.~~ R. ~~26 & 27 W.~~ 4th p. Mer.
~~1/4~~ Corner common to Sections
~~1~~, and ~~6~~


Corner consists of a ~~iron pipe 2 aspen post~~ place
State condition ~~good~~

Dimensions above ground ~~pipe 4x6, post 3x3x30~~ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____
Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? **No**
If not, why? ~~Set by proportional measurement~~
~~No OLC corner found.~~

John P. ...
(Signature)

2/15/38
(Date)

Jr. Asst. Tech.
(Title)
2-7394

C-25

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.04

from which this Corner bears

N 130 E


side of

11 in

tree 4 inches diameter, on the west

Aspen

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

4th P.

R. 26-27N

T. 57N