

U. S. Department of Agriculture

FOREST SERVICE

PP

Chippewa NATIONAL FOREST A 25

CORNERS OF THE PUBLIC SURVEY

T. 57-58 R. 26-27 4th Mer.

Township Corner common to Sections

1, 6, 31, and 36

Corner consists of a Tam. stake & Iron pipe in place

State condition good

Dimensions above ground 5x6x24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S 36	S 1	S 6	S 31
---------	--------	--------	---------

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

JBR

T58N. R27W. S.36	T.58N. R.27W. S.36		
BT	BT		

Species Spruce Tam. stub 14' high Spruce

Diameter 9" 6" 6"

Bearing N24°30'W. N21°E. S38°W.

Distance 94 lk. 50 lk. 69 lk.

Do you believe this to be a genuine Land Office Corner? **Yes**  
 If not, why? **Stake and BT's are not original.**  
**However, I found what I believe to be a**  
**piece of original stake buried in pre-**  
**sent location.**

(Signature)

9/1/37


JR. Assist. to Tech.

(Date)

(Title)

(Make sketch of topography near Corner)

T. 57-58 R. 26-27 4th Mer.



Metal Location Poster is on a

tree 5 inches diameter, on the north

side of line

from which this Corner bears N56° E

0.25

chains distant.

Give any further facts which will aid in finding this

Corner again.

Corner is in swamp ground containing

spruce, birch, aspen, & cedar.

Rangers copy

U. S. Department of Agriculture  
FOREST SERVICE

A-27

A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57-55 R. 26-27 4 Mer.

Section Corner common to Sections

31, 6, 1, and 36

Corner consists of a: Tamarack (not) in place



State condition Good

Dimensions above ground 4x4x36 & iron pipes

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species E. Pine

Diameter 24"

Bearing N. 13W.

Distance .91

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Robt. Broadbridge

(Signature)

6/25/36

(Date)

Fore. of Survey crew


(Title)

ph W. M.

A-25

T. J. crosses line six chains north of corner. Corner again.

Give any further facts which will aid in finding this chains distant. From which this Corner bears side of line tree 9 inches diameter, on the Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57-58 R. 26-27 Mer.

Section

Corner common to Sections

51, 6, 1, and 25

Corner consists of a Timber (not) in place



Stone condition

Dimensions above ground 4x4x4 & Iron pipe

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of None is located

Pits are located None

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species H. Pine

Diameter 24"

Bearing N. 15°

Distance .91

Do you believe this to be a genuine Land Office Corner?

If not, why?

BT's not GLO. Log 8/24/37

1/20/30

Habt. Broadbridge

(Signature)

Fore. of Supply

(Title)

(Date)

A-25

chains north of corner.  
T. 57-58 R. 26-27

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

S. 511.

side of


line

tree 8 inches diameter, on the east

side

Metal Location Poster is on a

corner



(Make sketch of topography near Corner)

Mer.

4

T. 57-58 R. 26-27