

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

A-3

----- NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 58/59 R. 25 Mer.

----- Corner common to Sections  
N 1/4 of S. 6, and S. 31

Corner consists of a Iron Pipe 2" (not) in place  
 State condition good - stamped on cap

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species W. Sp. W Sp.  
 Diameter 6" 6"  
 Bearing S 85 W N 60 E  
 Distance 2 FL 12 FT

Do you believe this to be a genuine Land Office Corner? -----

If not, why? Set by cavity survey crew in 1954

R. H. Christopher  
 (Signature)

7-15-54  
 (Date)

Dist. For. Rgr.  
 (Title)

-----

-----

-----

-----

-----

-----

-----

-----

about north of corner.

Cut out line to about

Corner again.

Give any further facts which will aid in finding this


105 FT. <sup>or more</sup> distant.

from which this Corner bears East

side of road

tree 4 inches diameter, on the east

Metal Location Poster is on a <sup>block</sup>



(Make sketch of topography near Corner)

Mer.

R.

T.