

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

A-9

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 R. 25 Mer.

Corner common to Sections

4, 5, 32, and 33

Corner consists of a Iron Pipe - Copied in place

State condition good

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Sketch</u>			
---------------	--	--	--

--	--	--	--

Species Balsam Balsam Birch Cedar

Diameter 10" 8" 4" 8"

Bearing S 80 W N 70 W S 90 E N 15 E

Distance 40' 15' 25' 45'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No. Set by county in

1954

Ralph H. Christensen

(Signature)

12-14-54

(Date)


D. F. Ryan

(Title)

South edge of spruce swamp
3 1/2 the north of corner line
Corner again.

Give any further facts which will aid in finding this
chain distant.
from which this Corner bears
side of
tree inches diameter, on the

Metal Location Poster is on a *Bush B.T.*



(Make sketch of topography near Corner)