

U. S. Department of Agriculture
FOREST SERVICE

B-11

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 W 4th Mer.

VA Corner common to Sections
21, and 22



Corner consists of a 4" TAM (not) in place
State condition good.

Dimensions above ground 29 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? This is a private placed cor. on the edge of the Trout Lake Estate


Emin Meagher
(Signature)

10-23-34
(Date)

Field Ass't
(Title)

Corner again.
CORNER IS IN OPEN SPACE
OF ABOUT 3A. WHICH
USED TO BE A OLD
LOGGING CAMP SITE

Give any further facts which will aid in finding this
347.1. ~~thence distant.~~
from which this Corner bears N12°E
side of TREE
tree 8 inches diameter, on the N.E.
Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 58 N. R. 25 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

R-11

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 W 7th Mer.

17 Corner common to Sections
21, and 28

Corner consists of a 4" tan (rod) in place
State condition good

Dimensions above ground 2' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? This is a private placed on the edge of Trout Lake estate


Bruce Mesher
(Signature)

10-23-34
(Date)

Field asst
(Title)

Corner again.
cot is in open space
of about 3 A. which
used to be an old
logging camp site

Give any further facts which will aid in finding this
34 LI. ~~chain~~ distant.
from which this Corner bears
N 12° E
side of tree
tree 8 inches diameter, on the
Metal Location Poster is on a
ASPEN N.E.



(Make sketch of topography near Corner)

T. 58 N. R. 25 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Posted.
Chippewa NATIONAL FOREST R11

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 W 4th Mer.

VA Corner common to Sections
_____, _____, 21, and 28

Corner consists of a 4" tan ~~rod~~ in place
State condition good

Dimensions above ground 29 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? This cor. is a private placed cor. on the edge of the Trout Lake Estate


Erwin Meagher
(Signature)

10-23-54
(Date)

Field Ass't
(Title)

Corner again.
 COR IS IN OPEN SPACE
 OF ABOUT 3 A. WHICH
 USED TO BE AND OLD
 LOGGING CAMP SITE.

Metal Location Poster is on a ASPEN tree 8 inches diameter, on the side of tree from which this Corner bears N 12° E 34 LI. (points distant).
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 58 N. R. 25 W. 4th Mer.