

Form 874-9--Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

A-11

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 R. 25 Mer.

$\frac{1}{4}$ Corner common to Sections
4, 33, and

Corner consists of a Iron Pipe (not) in place

State condition good

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Birch R.O.O.

Diameter 5" 4"

Bearing S N

Distance 13' 50'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No - set in 1954

by county

R. H. Christopher
(Signature)

12-14-54
(Date)

D. F. R.
(Title)

1/2 the width of front line


Corner again.

Give any further facts which will aid in finding this

chains distant.

From which this Corner bears *East - 51°* side of

Metal Location Poster is on a *Black* tree *4* inches diameter, on the *south*



(Make sketch of topography near Corner)