

U. S. Department of Agriculture
FOREST SERVICE

C-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 25 Mer.

Center = 1/4 Corner common to Sections
2, _____, _____, and _____


Corner consists of a Iron Pipe (not) in place
State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No

Set in 1954

Ralph H. Christopher
(Signature)

D. F. R.
(Title)

12-2-54
(Date)

Transect line N-E-W

Corner again.

Give any further facts which will aid in finding this

~~corner distant.~~

6/14

from which this Corner bears

No. 75

side of

tree *8* inches diameter, on the

Metal Location Poster is on a *Aspen*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

C-19

Mer. R. T.