

U. S. Department of Agriculture  
FOREST SERVICE

5-25  
S-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 29E 25W 9TH Mer.

N 1/16 Corner common to sections  
25, and 30

Corner consists of a 2" scribed post (not) in place

State condition Good

Dimensions above ground 36 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Not a Land Office Corner  
set by County Surveyor

Arthur J. Johnson

(Signature)

2/16/40

(Date)

Edward Jensen

(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


chains distant. 27'

from which this Corner bears N 79° E

side of

tree 6 inches diameter, on the

Metal Location Poster is on a H.S. 8.00



(Make sketch of topography near Corner)

T. 58 N R. 22 E W 9TH Mer.