

U. S. Department of Agriculture  
FOREST SERVICE

F-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24-25 W 4th p Mer.

N 1/16 Corner common to Sections

7, and 12

Corner consists of a Aspen post ~~(not)~~ in place



State condition New

Dimensions above ground 3 x 4 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species None

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? Set by me by proportional measurement.

Seth W. Peterson  
(Signature)

5/13/38  
(Date)

Jr. Asst. to Tech.  
(Title)

1 2

Corner again.

Give any further facts which will aid in finding this


0.31 chains distant.

from which this Corner bears S 64° E

side of Line

tree 4 inches diameter, on the East

Aspen Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 58 N R. 24-25 W 4th P Mer.