

U. S. Department of Agriculture
FOREST SERVICE

A-25
A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 N. R. 24-25 W. 4th p. Mer.

Township Corner common to Sections

1, 6, 31, and 36

Corner consists of a ~~Aspen post & Pipe~~ ^{iron} in place

State condition Post-new, pipe good 4x4x36

Dimensions above ground Pipe 4x16, Post- inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Govt. BT	T59N R24W S31		
	BT		

Species	W.P. Stump	W. Spruce	Asp	Bals	Bals
Diameter	24	6	7	8"	9"
Bearing	N55° W	N75° E	S20 W	N15 W	S45 E
Distance	17	25	12'	16'	26'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Reestablished by county surveyor about 1915

New B.T.s in 1954 - R. W. Peterson


Seth W. Peterson
(Signature)

May 27, 1935
(Date)

Jr. Asst. to Tech.
(Title)

(Make sketch of topography near Corner)

T. 58-59 N. R. 24-25 W. 4th P. Mer.



Metal Location Poster is on a Aspen ~~tree~~

tree 6 inches diameter, on the

side of

from which this Corner bears

N30°

chains distant.

0.19

Give any further facts which will aid in finding this

Corner again.

Treatise N-S-E-W

Five