

U. S. Department of Agriculture  
FOREST SERVICE

*A-6*  
*A-6*  
*West M.C. 02-7*  
*Gun*  
*Lot*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 R. 25 Mer.

M.C. Corner common to Sections  
32, and 5

Corner consists of a Iron pipe (not) in place  
State condition good

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Scrub</u>			

Species Cedar

Diameter 10

Bearing 390w

Distance 15

Do you believe this to be a genuine Land Office Corner? No

If not, why? Set by county - 1884

Ralph W. Christensen

(Signature)

D.F.R.

(Title)

12-14-54

(Date)

water

Pipe is 10 FT from open

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears East 10 FT

side of

tree 4 inches diameter, on the East

Metal Location Poster is on a Cedar

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)