

U. S. Department of Agriculture
FOREST SERVICE

A-15-16

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 25 Mer.

Mc-East side of Wagon wheel lake. Corner common to Sections

3, 09, Tuphine, and

Corner consists of a Pipe-capped ~~rod~~ in place


State condition good

Dimensions above ground 2 1/2" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Birch

Diameter 8" 6"

Bearing E SE

Distance 4' 35'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Set 1954 by county

Ralph W. Christensen

(Signature)

D. F. Rys.


(Title)

12-17-54
(Date)

Corner again.
 Long bear hour 30' South
 of Top on left

Give any further facts which will aid in finding this
 chains distant.

from which this Corner bears
 side of ~~Top~~
 tree 7 inches diameter, on the ~~spot~~
 Metal Location Poster is on a ~~BTS + BSpur~~



(Make sketch of topography near Corner)