

U. S. Department of Agriculture
FOREST SERVICE

C-14-20

..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 25 Mer.

..... Corner common to Sections

2,, and Interior N.C.

Corner consists of a pipe (not) in place


State condition good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why? No - Set in 1954

Ralph W. Smith
(Signature)

12-7-54
(Date)

.....
(Title)

line cut to west.

about 9 FT from western edge

South of a cabin and is

Pipe is about 130 FT

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

Not.



(Make sketch of topography near Corner)

C-19,20

Mer.

R. 25

T. 28

T.