

U. S. Department of Agriculture
FOREST SERVICE

J-22423

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 25 W. 4th P. Mer.

Meander

Corner common to sections

12, and 13 (W. bank)

Corner consists of a aspen post (500) in place

State condition good

Dimensions above ground 3 1/2 x 3 1/2 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

MC		MC	
S		S	
12		13	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		Other	
		BT location	
		covered by	
61		muskrat	house

Species Tam. Stump

Diameter 6"

Bearing S58°W

Distance 0.42 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Seth W. Peterson

(Signature)

4/20/38

(Date)

Jr. Assist. to Tech.

(Title)

corner is on narrow strip of land
stamp between lake and to highland.

Corner again.

Give any further facts which will aid in finding this


0-34 chains distant.

from which this Corner bears N. 54° E.

side of B-1 Stamp

tree 4 inches diameter, on the Northeast

Metal Location Poster is on a black spruce



(Make sketch of topography near Corner)

T. 22 N. R. 25 W. 4th P. Mer.