

U. S. Department of Agriculture
FOREST SERVICE

TU-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 29&25W 9th Mer.

Meander Corner common to Sections
25, and 30

Corner consists of a None (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Tom. Stob _____

Diameter 12" _____

Bearing N 25° W _____

Distance 30 lks. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur J. Johnson

(Signature)


Squad Foreman

(Title)

2/15/90

(Date)

(Make sketch of topography near Corner)



T. 58N R. 24E W. 9TH Mer.

Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

This corner lies between south of
Cutaway Road on North side of upper
Hanson Lake

U. S. Department of Agriculture
FOREST SERVICE

57
T+U-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 29E 25W 4th Mer.

Meander Corner common to sections
25, and 30

Corner consists of a None (not) in place

State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Tom. Stub*

Diameter *12"*

Bearing *N25°W*

Distance *30 1/2*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Arthur J. Johnson

(Signature)

Special Foreman


(Title)

2/15/40

(Date)

Corner again.
This corner is 8 chains south
of Gateway Road on North side
of Upper Hanson Lake

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 5 N R. 24 W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST T-U 25

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 29&30W 4th Mer.

Meander Corner common to Sections

25, and 30

Corner consists of a None (not) in place

State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Tan. Stub

Diameter 12"

Bearing N25°W

Distance 30 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur J. Johnson

(Signature)

Special Foreman


(Title)

2/15/40

(Date)

(Make sketch of topography near Corner)

T. 58N R. 29E 25W 9th Mer.



Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

chains distant.

Give any further facts which will aid in finding this

Corner again.

This Corner lies 8 chains south of
Gulaway Road on North side of Upper
Hanson Adks.