

Rangers copy

Form 874-6--Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 52 R. 26-27 4 Mer.
1/4 corner on R. line Corner common to Sections
31, T. 58, R. 26, and 36-58-27

Corner consists of a Cedar (not) in place
State condition Good

Dimensions above ground 4x4 by 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4		1/4
	31		36

N W S E NW SW SE NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BT			

Species White Pine stump

Diameter 12"

Bearing S. 65 E.

Distance 55

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walt Broadbridge

(Signature)

6/24/36

(Date)

foreman of survey crew

(Title)

Evidently Good bridge at the cedar stake
near pipe found N. 1.0. field notes - Kunkelouch

ground.

Iron pipe two inches out of

Corner again.

Give any further facts which will aid in finding this


.45 chains distant.

from which this Corner bears N. 11 E.

side of line

tree 8 inches diameter, on the west

Metal Location Poster is on a N. Aspen



(Make sketch of topography near Corner)

Supervisor's Copy

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST X I
CORNERS OF THE PUBLIC SURVEY

T. 22 R. 26-27 4 Mar.
1/4 corner on R. line Corner common to Sections
31 T. 55 R. 26, and

Corner consists of a Cedar (not) in place
State condition Good

Dimensions above ground 4x4 by 36" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

1/4	1/4
31	36
N	E
W	S

NW	SW	SE	NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

57			

Species White Pine stump

Diameter 18"

Bearing S. 65 E.

Distance 55

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Scott. Broadbridge

(Signature)

FOREMAN OF SURVEY

6/24/36

(Date)

(Title)

pu N. M.

Endorsed by Standard bridges at the sides of the
- iron pipe from N.D.O. field notes - Standard

ground.

Iron pipe two inches out of

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


N. 11 E.

side of

line

tree 8 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)