

Rangers copy

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

23-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26-27 4 Mer.
N. 1/16 on Range line Corner common to Sections
31, T. 58, R. 26, and Sec. 36, T. 58, R. 27

Corner consists of a Tamarack (not) in place

State condition Good

Dimensions above ground 4x4 by 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/16		1/16
	31		36

N W S E

NW SW SE NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BT			

Species Spruce stump

Diameter 9"

Bearing N. 30 W.

Distance 26

Do you believe this to be a genuine Land Office Corner? No

If not, why? 1/16 corner not in original survey. 30" stake and iron pipe 6" high.

R. Broadbridge H.B.

(Signature)


Foreman of survey crew.

8/24/36

(Date)

(Title)

road.
 and two chains north of old logging
 About the center of 7-b swamp
 Corner again.
 Give any further facts which will aid in finding this
 • 15' chains distant.
 from which this Corner bears N. 43° W.
 side of Line
 tree 6 inches diameter, on the East
 Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

Supervisor's copy

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 53 R. 26-27 4 Mer.
N. 1/16 on Range line Corner common to Sections

31, T. 53, R. 26, and Sec. 36, T. 53, R. 27


Corner consists of a Tamarack (not) in place
State condition Good

Dimensions above ground 4x4 by 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce stump

Diameter 9"

Bearing N. 30 W.

Distance 26

Do you believe this to be a genuine Land Office Corner? No.

If not, why? 1/16 corner not in original survey. 30" stake and iron pipe 6" high.

6 / 24 / 36


(Date)

P. Broadbridge
(Signature)
Foreman of survey crew

(Title)

road.
 and two chains north of old logging
 Corner again about the center of 7.9 swamp
 Give any further facts which will aid in finding this
 chains distant.

from which this Corner bears
 N. 45 W. 45 ft.
 tree inches diameter, on the
 Metal Location Poster is on a East
 Spruce



(Make sketch of topography near Corner)