

35

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 7 Mer.

1/16 #12 #6 Corner common to Sections
_____, _____, 31, and _____

Corner consists of a Cedar (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--------|--|------|--|
| P. 185 | | NONE | |
| | | | |

Species ASPEN

Diameter 5"

Bearing S20W

Distance 64/ks

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Put in by JUREAN

O. Jurean

(Signature)

J. S. Farn

(Title)


6/23/26
(Date)

Corner again. 3 chs. 50. as a lake on top of a high hill

Give any further facts which will aid in finding this 64 chains distant.

from which this Corner bears S 20° W side of E side of line

tree 5 inches diameter, on the West Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Y
-3



Shippore NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 22 Mer. 4
52 1/16 (1/16) Corner common to Sections
51, _____, and _____

Corner consists of a Corner (not) in place
State condition Good


Dimensions above ground 30" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of None is located _____

Pits are located None

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen

Diameter 5"

Bearing S. 30 W.

Distance 44

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Put in by OTTON JENSEN, JR. Foreman

6/26/36
(Date)


O. Jensen
(Signature)
Const. Foreman
(Title)

Corner again.
This 1/16 corner is three chains
south of a lake on top of a high hill.

Give any further facts which will aid in finding this
chains distant.

from which this Corner bears
3. 50 N.

tree 5 inches diameter, on the E. side of tree
East side of line
Metal Location Poster is on N. corner



(Make sketch of topography near Corner)

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Y-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 4 Mer.

CS 1/16 # 12 Corner common to Sections 31, and

Corner consists of a Cedar (not) in place



State condition Good

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen

Diameter 5"

Bearing S. 20 W.

Distance .64

Do you believe this to be a genuine Land Office Corner?

If not, why?

Put in by Orron Juneau, Jr. Foreman

Orron Juneau

(Signature)


Foreman

(Title)

4/26/36

(Date)

Metal Location Poster is on an Aspen tree 5 inches diameter, on the W. side of tree side of East side of line from which this Corner bears S. 20 W. *64 chains distant. Give any further facts which will aid in finding this Corner again. This 1/16 corner is three chains south of a lake on top of a high hill.



(Make sketch of topography near Corner)