

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST 211
CORNERS OF THE PUBLIC SURVEY

T. *58N.* R. *26W.* *4th* Mer.

1/4 Corner common to Sections
33, and *4 T. 57N. 26W. 4th M.*

Corner consists of a *4 balsom post (not)* in place
3 cornered iron pin
State condition *good*

Dimensions above ground *post 40" dia 8* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>S</i> <i>33</i>		<i>S</i> <i>4</i>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>S</i> <i>33</i>		<i>S</i> <i>4</i>	
<i>B.T.</i>		<i>B.T.</i>	

Species *W. birch* *W. birch*
 Diameter *5"* *6"*
 Bearing *N. 25° E* *S. 29° W*
 Distance *70 links* *24 links*


Do you believe this to be a genuine Land Office Corner? *yes*
If not, why? _____

Ernest Perre
(Signature)
Field Asst.
(Title)

10-3-34
(Date)

Corner again.
CORNER IS LOCATED 1 CHAIN N.
OF SPRUCE SWAMP BEARING E.W.

Give any further facts which will aid in finding this
R. Blinck's chains distant.
from which this Corner bears S. 4° E.
side of tree
tree inches diameter, on the S. E.
Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T 58 N. R. 26 W. 4 1/2 Mer.