

Superior copy

U. S. Department of Agriculture
FOREST SERVICE

P

Chippewa NATIONAL FOREST

#13

CORNERS OF THE PUBLIC SURVEY

T. ⁵⁸57 N. R. 26 W. 4th Mer.
Section

Corner common to Sections
3, 4, 33, and 34

Corner consists of a 4" Balsam stake (not) in place



State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



JSH N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Stake evident but scribing rotted



Stake evident but scribing chopped out



Species Balsam fir W. Birch

Diameter 7" 8"

Bearing S 60° E N 54° E

Distance 0.56 chs. 0.30 chs.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Former report by Ernest Perry stated that scribing on birch was plainly evident - has recently been chopped away. Located Balsam B.T. from S.L.O. notes.

Charles J. Knoll
(Signature)

Junior Forester
(Title)

July 19, 1937
(Date)

Give any further facts which will aid in finding this corner again. Other metal location poster is on dead 9" w/h. pine from which this corner bears $S 6^{\circ} W 42$ links.

Corner is at intersection of original N 2 S, E 2 W, 1/2 league line. A 9" white pine 4 links S. of corner from long logs facing corner. 10 w/h. pine 3 links west of corner from logs on W. side. w/h. spruce mentioned above has 2 old logs facing corner. Balam B. T. almost rotted away - a fallen birch protected upper box.


0.25 chains distant.

from which this corner bears $S 50^{\circ} W$

side of tree

tree 14 inches diameter, on the SW

Metal Location Poster is on a white spruce



(Make sketch of topography near corner)