

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST *A13*

CORNERS OF THE PUBLIC SURVEY

T. *58N* R. *26W* *4th* Mer.

Section Corner common to Sections
33, *34*, *3*, and *4*

Corner consists of a *4" balsam post (wot)* in place
State condition *good*

Dimensions above ground *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S 33	S 4	S 3	S 34
---------	--------	--------	---------

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 33

S 4

S 3

S 34

--

--

--

B.T.

Species _____ *W. birch*

Diameter _____ *8"*

Bearing _____ *N. 20° E.*

Distance _____ *58 links*

Do you believe this to be a genuine Land Office Corner? *Y. S.*

If not, why? *Note. Found old gov. B.T. with scribing plainly visable and re-estb temp. post by refering to gov. field notes.*


Ernest Perry
(Signature)

10-3-34
(Date)

Field asst
(Title)

Corner is located 10.95
chains South of spruce swamp
brs. E & W
Corner again.

Give any further facts which will aid in finding this
9 links chains distant.
from which this Corner bears N 45
side of tree
tree 2 inches diameter, on the N.E.
Metal Location Poster is on a W pine



(Make sketch of topography near Corner)

T. 58N R. 26W 4th Mer.