

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST Z 25



CORNERS OF THE PUBLIC SURVEY

T. 58N R. 29+25W 4th Mer.

1/4 Corner common to Sections
31, and 36

Corner consists of a 1" Iron Pipe (not) in place
State condition


Dimensions above ground 8 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.




Species
Diameter
Bearing
Distance

Do you believe this to be a genuine Land Office Corner? No
If not, why? Records show it was set by
County Surveyor.

Arthur J. Johnson
(Signature)
Special Foreman
(Title)

2/15/40
(Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

T. 58N R. 24+25W 976 Mer.