

U. S. Department of Agriculture
FOREST SERVICE

F-25

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24-25 4th Mer.

N 1/16

Corner common to sections

7, and 12

Corner consists of a ~~Aspen post~~ (net) in place



State condition ~~new~~

Dimensions above ground 3 x 4 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ~~None~~

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? ~~no~~

If not, why? ~~set by no by proportional measurement.~~

~~Seth A. Peterson~~
(Signature)

5/13/38
(Date)

~~Jr. Asst. to Tech.~~
(Title)

Corner again.

Give any further facts which will aid in finding this


0.31 chains distant.

from which this Corner bears S 64° E

side of 11m

tree 4 inches diameter, on the East

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)