

U. S. Department of Agriculture
FOREST SERVICE

A-10-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 NR. 26 W. 4th Mer.

----- M.C. ----- Corner common to Sections
-----, -----, 4, and 33-----

Corner consists of a 3" Cedar (not) in place
State condition good (1" iron pipe 6")

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 33		S 4	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 4	
		B.T.	

Species ----- W. Birch

Diameter ----- 6"

Bearing ----- S. 59° W

Distance ----- 14 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

Erwin Mergler
(Signature)

1-11-35
(Date)

Field ass't
(Title)

Corner again.

Give any further facts which will aid in finding this


~~chain~~ distant.

from which this Corner bears $N 59^{\circ} E$

side of ~~tree~~

tree 6 inches diameter, on the N.E.

Metal Location Poster is on a W. BIRCH



(Make sketch of topography near Corner)

T58-59N R. 26W 774 Mer.

U. S. Department of Agriculture
FOREST SERVICE

Posted

CHIPPewa NATIONAL FOREST A 10-11
CORNERS OF THE PUBLIC SURVEY

T. 58-59 NR. 26 W. 4th Mer.

M. C. Corner common to Sections

, 4, and 33

Corner consists of a 3" cedar (not) in place

State condition good (1" iron pipe 6")

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
33		4	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S		S	
33		4	
B.T.		B.T.	

Species _____ W. Birch

Diameter _____ 6"

Bearing _____ S 59° W

Distance _____ 17 Li

Do you believe this to be a genuine Land Office Corner? **YES**

If not, why? _____

Erwin Meagher
(Signature)Field ass't
(Title)1-11-35
(Date)

Corner again.

Give any further facts which will aid in finding this

~~corner~~ distant.

147!


N59°E

from which this Corner bears

side of trees

tree 6 inches diameter, on the N.E

Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T. 58-59 N. R. 26 W. 774 Mer.

U. S. Department of Agriculture
FOREST SERVICE

A-10-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 N. 26 W. 4th Mer.

M. C. Corner common to Sections
.....,, 4, and 33

Corner consists of a 3" Cedar (not) in place
State condition good (iron pipe 6")

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 33		S 4	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 33		S 4	
B.T		B.T	

Species W. Birch

Diameter 6"

Bearing S. 59° W

Distance 14 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

E. M. McHugh


(Signature)

Field Ass't

(Title)

1-11-35
(Date)

Metal Location Poster is on a *W. Birch* tree *6* inches diameter, on the *N.E* side of *tree* from which this Corner bears *14 L!* *obscure distant.* Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 58-59 N R. 26 W 4th Mer.