

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 & 59N. R. 26W. 4th P. Mer.

Meander Corner common to Sections

4, and 33

Corner consists of a iron pipe & Aspen post

State condition Good

Dimensions above ground Pipe 1x6, post 4x4x30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 33		S 4	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

MC S. 4 BT	MC S 4	Scribing rotted off	
	BT		

Species Birch Birch Ash

Diameter 8" 6" 4"

Bearing S63°W S11°W S44°E

Distance 0.14ch 0.48ch 0.12ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Seth W. Peterson

(Signature)

3-1-38

(Date)


Jr. Asst. to Technician

(Title)

West bank North Star Lake. Band Tap.
Line brushed out 0.30 ch. S. of corner.
Corner again.

Give any further facts which will aid in finding this
chains distant.

0.14
from which this Corner bears
R. 89° E.
side of brushed-out line
inches diameter, on the
North
Metal Location Poster is on a Birch B.T.



(Make sketch of topography near Corner)

T. 58.59N. R. 26W. 4th P. Mer.