

Rangers
copy

U. S. Department of Agriculture
FOREST SERVICE

Y-2



Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.
SW 1/16
31 Corner common to Sections
and

Corner consists of a 4th Spruce Post (not) in place
State condition Good

Dimensions above ground 25 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 # 5	1/16 # 5		
B.T.	B.T.		

Species	Spruce	Spruce	
Diameter	6	5	
Bearing	S13E	N50W	
Distance	32 Lks	14 Lks	

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner set by County
Surveyors and bearing trees
scribed by same

J. C. Murbeck
(Signature)

12/21/36
(Date)

(Title)

Corner Post is located in
a spruce swamp.
Bearing trees in good
condition.

Corner again.

Give any further facts which will aid in finding this


321K5 ~~changes distant.~~

from which this Corner bears N 13 W

side of Tree

tree 6 inches diameter, on the north

Metal Location Poster is on a spruce



(Make sketch of topography near Corner)

T. 59 R. 26 1th Mer.

super visors
copy

U. S. Department of Agriculture

FOREST SERVICE

Y-2

Shippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

SW 1/16 Corner common to Sections 31, , , and

Corner consists of a 1" Spruce Post (not) in place

State condition Good

Dimensions above ground 25 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16
#5

1/16
#5

BT

BT

Species Spruce Spruce

Diameter 6 5

Bearing S13E N50W

Distance 321ks 141ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner set by County

Surveyors and Bearing

Trees scribed by same

J. C. Murbeck

(Signature)


12/2/36

(Date)

(Title)

Corner again.
Corner Post is located in
a Spruce Swamp in good
bearing trees in good
condition.

Metal Location Poster is on a Spruce
tree 6 inches diameter, on the north
side of Tree
from which this Corner bears
32 MKS ~~claims~~ distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 59 R. 26 4th Mer.