

U. S. Department of Agriculture
FOREST SERVICE

R-2

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 36 W 4 P. Mer.

W 1/16 Corner common to Sections
19, and 30

Corner consists of a 3" cedar (not) in place

State condition Just placed

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W 1/16		W 1/16	
519		519	
230		+30	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? F.S.

George W. Jennings

(Signature)

9-14-35


(Date)

Const. Insp. C. M.

(Title)

Corner again.
Small creek 1/2 ch. E.
Stake is 1/2 ch N of picket line

Give any further facts which will aid in finding this
0.18 chains distant.
From which this Corner bears N20W
side of tree
tree 7 inches diameter, on the N
Metal Location Poster is on a TAMARACK



(Make sketch of topography near Corner)

T. 59 R. 26 Mer. 4