

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

C 1/4 Corner common to Sections
19, and

Corner consists of a Cedar Stake (not) in place
State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S.

George D. Jennings
(Signature)

9-24-35
(Date)

Jr. Foreman C&M
(Title)

Corner again.
Near crossing of picket lines. Several cedars 10"

Give any further facts which will aid in finding this

chains distant.

From which this Corner bears

N50E


side of

tree

tree 9 inches diameter, on the

NE

Metal Location Poster is on a W. Cedar



(Make sketch of topography near Corner)

T. 59N R. 26W 4th Mer.