

U. S. Department of Agriculture

FOREST SERVICE

0-5

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P Mer.

N 1/16

Corner common to Sections

19, and 20

Corner consists of a 5" Cedar (not) in place

State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	N 1/16		N 1/16
	S		S
	19		20


N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? Co. Cor. Post is set off to W side of abandoned road

George H. Jennings

(Signature)

8-30-35

(Date)

Jr. Brecken C & M

(Title)

Blank lined area for notes at the top of the page.

of standard road

Foster is on E Side

Corner again.

Give any further facts which will aid in finding this

chains distant.

30

from which this Corner bears

N 80 W

side of


tree

tree 4 inches diameter, on the W

W

Metal Location Poster is on a

Aspen



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4149 Mer.