

U. S. Department of Agriculture
FOREST SERVICE

A-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

Section Corner common to Sections
31, 32, 5, and 6

Corner consists of a bleeder post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S 31	S 6	S 6	S 32
------	-----	-----	------

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 60N R 26W S 31	T 60N R 26W S 32	T 59N R 26W S 5	

Species Birch Cedar Birch

Diameter 9" 8" 11"

Bearing N 40° W N 25° E S 30° E

Distance 334 754 914

Do you believe this to be a genuine Land Office Corner? No


If not, why? Scribbling on witness trees shows age to be about 10 yrs ago; probably County No. 13.1. at date of trees

H. Moor
(Signature)
Feb 7, 1935 Technical Foreman
(Date) (Title)

Corner again.
 line tree on lake shore
 is old blazed white pine
 stub 20' high.

Give any further facts which will aid in finding this
 chains distant.

Metal Location Poster is on a white birch
 tree 9" inches diameter, on the
 side of Bearing tree
 from which this Corner bears
 S 40° E



(Make sketch of topography near Corner)

T. 5 N - 60 N R. 26 W Mer.