

U. S. Department of Agriculture

FOREST SERVICE

J-6

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 444 P. Mer.N 1/4 Corner common to Sections
-----, -----, 8, and 17Corner consists of a ----- (not) in place
State condition -----

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

George J. Dunning

(Signature)

8-2-35

(Date)

Forest Supervisor C+M


(Title)

Corner again.
On old highway grade.
The tele pole

Give any further facts which will aid in finding this
 chains distant.

From which this Corner bears
133
54° 30' W
 side of pole

tree inches diameter, on the
5
 Metal Location Poster is on a
Tele Pole



(Make sketch of topography near Corner)

T. 59N R. 26W 44E Mer.