

U. S. Department of Agriculture  
FOREST SERVICE

G-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th P. Mer.

C 1/4

Corner common to Sections

8, and

Corner consists of a Cedar Stake (not) in place

State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S

George H Jennings  
(Signature)

9-35  
(Date)

Jr. Foreman  
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.24

from which this Corner bears 560 W

side of tree

tree 5 inches diameter, on the SW

Metal Location Poster is on an Aspen

	Sec.		Sec.
	Sec.	Sec.	

(Make sketch of topography near Corner)

T. 59 R. 26 Mer. 446 P