

U. S. Department of Agriculture
FOREST SERVICE

0-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

So. 1/16 Corner common to Sections
-----, -----, 20, and 21-----

Corner consists of a 4" b. ash post (not) in place
State condition good 3/4 iron pin.

Dimensions above ground post 30" pin 10" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S.20		S.21
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S.20		S.21
	B.T.		B.T.

Species	<u>Baham</u>	<u>W. Birch</u>
Diameter	<u>7"</u>	<u>5"</u>
Bearing	<u>N. 62° W</u>	<u>N. 10° E</u>
Distance	<u>23 Links</u>	<u>23 Links</u>

Do you believe this to be a genuine Land Office Corner? -----

If not, why? County Re-survey corner

E. Perry

(Signature)

Field Asst.

(Title)

5/14/35
(Date)

Faint, illegible text on ruled lines at the top of the page.

Corner again.

Give any further facts which will aid in finding this


23 links chains distant.

from which this Corner bears *S 62° E*

side of *tree*

tree *7* inches diameter, on the *S.E.*

Metal Location Poster is on a *balcon*



(Make sketch of topography near Corner)

T 59N R 26W Mer. 44

U. S. Department of Agriculture

FOREST SERVICE

Q-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 Mer.

116 #14 So 1/4 Corner common to Sections

20, and 21.

Corner consists of a 4" Black + Iron pin (not) in place


State condition good

Dimensions above ground 30 pint inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam W Birch

Diameter 7" 5"

Bearing N62°W N10°E

Distance 23 ch. 23 ch.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? County Resurvey

PERRY (Signature)

Field Ass't. (Title)


6/14/35 (Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears
side of
tree 7 inches diameter, on the
Metal Location Poster is on a
34/54m



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

posted Q-9

CORNERS OF THE PUBLIC SURVEY

T. 39 R. 26 4th Mer.

S. C. 76 Corner common to Sections

20, 21 and 4" B. & B. Post
Corner consists of a 3/4" red pine (not) in place

State condition good

Dimensions above ground 3x3 post 30" pin 10 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

76c			
	S. 20		2.21

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

76c	S. 20		2.21
-----	-------	--	------

BT	BT		BT
----	----	--	----

Species Balsam W. Birch

Diameter 7" 5"

Bearing N. 62 W N. 10 E

Distance 23 lks. 23 lks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Resurvey case Ernest Perry Field Ass't.

5/14/35 James M. ... (Signature)

(Date) (Title)

Corner again.

Give any further facts which will aid in finding this


23 *1/2* chains distant.

from which this Corner bears *S 62 E*

side of *tree*

tree *7* inches diameter, on the *S. E.*

Metal Location Poster is on a *Balsam*



(Make sketch of topography near Corner)