

U. S. Department of Agriculture
FOREST SERVICE

0-97

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.



1/16 #7 Corner common to Sections
and 20

Corner consists of a 4" Spruce - 1 1/2" pipe (not) in place
State condition good

Dimensions above ground 3 1/2 feet 12 1/2 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Pine W. Pine

Diameter 7" 5"

Bearing N 61° E S 23° W

Distance 34 lks 38 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? County, Wisconsin

Data taken from ccc Survey Notes

by R. B. CENTERWELL

(Signature)

JUN. FORESTER

(Title)


7/15/27
(Date)

T

R

Mer.

(Make sketch of topography near Corner)



FOREST SERVICE
 U.S. DEPARTMENT OF AGRICULTURE
 SUPERVISOR
 WASE LAKE, MINN.
 JUL 19 1937
 RECEIVED

side of

three inches diameter, on the

Model Location Poster is on a

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

No metal location pins put in yet

Barber

U. S. Department of Agriculture
FOREST SERVICE

0-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *59 N* R. *26 W* Mer. *4*

1/16 # 7 Corner common to Sections
....., and *20*

Corner consists of a *4 1/2* ~~square~~ *Post* ~~iron~~ *Post* (not) in place
State condition *good*

Dimensions above ground *30* *x* *12* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	<i>W.P.</i>	<i>W.P.</i>
Diameter	<i>7"</i>	<i>5"</i>
Bearing	<i>N 61° E</i>	<i>S 23° W</i>
Distance	<i>34 1/2</i>	<i>38 1/2</i>

Do you believe this to be a genuine Land Office Corner? *no*
If not, why? *County ye survey*

Data Taken from cc Survey Notes.

P. B. CENTERMAN
(Signature)

7/15/32
(Date)

Jur. Forester
(Title)

I. C. MURBECK

no metal location: path cut by gale

Corner again.

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.
Give any further facts which will aid in finding this

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture
FOREST SERVICE

0-9

Chippewa NATIONAL FOREST**CORNERS OF THE PUBLIC SURVEY**T. 59 N. R. 26 W. 4th Mer.N. 1/4 Corner common to Sections-----, -----, 20, and 21Corner consists of a 4" spruce post (not) in placeState condition good 1" iron pipeDimensions above ground post 30" pipe 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION**DIAGONAL POSITION**

	S. 20		S. 21

N W S E

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S. 20		S. 21
	B.T.		B.T.

Species ----- W. pine ----- W. pineDiameter ----- 5" ----- 7"Bearing ----- S. 23° W. ----- N. 61° EDistance ----- 38 links ----- 39 linksDo you believe this to be a genuine Land Office Corner? NoIf not, why? COUNTY RESURVEY CORNERErnest Perry

(Signature)

Field asst.

(Title)

5/14/35

(Date)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


39 links distant.

from which this Corner bears 5.61° W.

side of tree

tree 7 inches diameter, on the S.W.

Metal Location Poster is on a W pine



(Make sketch of topography near Corner)

T. 59N. R. 26W. 4th Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

0-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4th Mer.
N. C. 1/4 Corner common to Sections

-----, -----, 20, and 21

Corner consists of a 7" Spruce post (not) in place
 State condition 1" Iron Pipe good

Dimensions above ground Post 36" pipe 10" inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION

	S. 20		S. 21
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S. 20		S. 21
	B. T.		B. T.

Species W. P. W. P.
 Diameter 5" 7"
 Bearing S. 23 W N. 61 E
 Distance 38 1/2 34 1/2

Do you believe this to be a genuine Land Office Corner? No
 If not, why? County Resurvey cor.

Ernest Perry.

(Signature)

Field Ass't.

(Title)

5/14/35
 (Date)

Corner again.

Give any further facts which will aid in finding this


34 1/2 chains distant.

from which this Corner bears S. 61 W.

side of trees

tree 9' inches diameter, on the S.W.

Metal Location Poster is on a W.P.



(Make sketch of topography near Corner)

T. 59 R. 26 Mer. 18 1/2