

U. S. Department of Agriculture  
FOREST SERVICE

K-9

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 39 N R. 26 W 4 P Mer.

1 1/2 Corner common to Sections  
16, and 17

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

*Henry J. Jennings*  
(Signature)

7-35  
(Date)

Const. Mgr. C & M  
(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.  
 About 30 chs. E of  
 fence corner


Give any further facts which will aid in finding this  
 0.09 chains distant.

from which this Corner bears  
 N 22 W

side of tree

tree 5 inches diameter, on the  
 NW

Metal Location Poster is on a  
 Balsam



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4 P Mer.