

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

Posted

R-10

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.W 1/2 Corner common to Sections
21, and 28Corner consists of a 4" bash post (not) in place
State condition good 3/4" iron pipeDimensions above ground post 36" pipe 8 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S. 21		S. 28	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

S. 21		S. 28	
B.T.		B.T.	

Species aspen _____ aspen _____Diameter 10" _____ 6" _____Bearing N 14° E _____ S 48° E _____Distance 38 links _____ 42 links _____Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

12-21-34 _____

(Date)

Ernest Perry

(Signature)


Field audit

(Title)

Metal Location Poster is on a *aspens* tree 10 inches diameter, on the *S.W.* side of *tree* from which this Corner bears *S. 19° N.* ~~38 links chains distant.~~

Give any further facts which will aid in finding this Corner again.

W 1/6 corner is located 820 chains west of highway #38.




(Make sketch of topography near Corner)

T. 59N R. 26W 4th Mer.

W. 1/6 corner is located 8.20 chains West of highway #38
Corner again.

Give any further facts which will aid in finding this
38 links ~~chain distance~~
from which this Corner bears S. 14° W.
side of tree
tree 10 inches diameter, on the S.W.
Metal Location Poster is on a 10" aspen



(Make sketch of topography near Corner)

T. 59N. R. 26W. 4th Mer.