

## U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

Posted

R-11

## CORNERS OF THE PUBLIC SURVEY

T. 59N. R. 26W. 4<sup>th</sup> Mer.1/4 Corner common to Sections21, and 28Corner consists of a 4" SPRUCE POST (not) in place  
1/2" IRON PIPE  
State condition goodDimensions above ground post 36" pipe 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 21		S 28	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 21		S. 28	
		B.T.	

Species \_\_\_\_\_ TamarackDiameter \_\_\_\_\_ 6"Bearing \_\_\_\_\_ S 72° EDistance \_\_\_\_\_ 16 linksDo you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Ernest Perry

(Signature)

Field ass't


(Title)

12-21-34

(Date)

Corner again.  
 1/4 corner is located in  
~~located in~~ 6 spruce swamp  
 which extends 11 chains  
 west & 1.50 chains east of  
 corner

Metal Location Poster is on a aspen  
 tree 6 inches diameter, on the SW  
 side of tree  
 from which this Corner bears 5.6 W  
 151 ft distant.



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

R-11

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEYT. 59N. R. R6W. 4<sup>th</sup> Mer.1/4 Corner common to Sections  
R1, and R8Corner consists of a 4" spruce post (set) in place  
1/4" iron pipe.  
State condition goodDimensions above ground post 36" pipe 6 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S.21		S.28	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.

S.21		S.28	
B.T.		B.T.	

Species \_\_\_\_\_ tamarackDiameter \_\_\_\_\_ 5 humpsBearing \_\_\_\_\_ 6"Distance \_\_\_\_\_ 5.72° EDo you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

12-21-34 \_\_\_\_\_

(Date)

(Signature)

Field

(Title)

Corner again.  
 1/4 corner is located in  
 b. spruce swamp which extends  
 11 chains west & 150 chains  
 East of corner.

Give any further facts which will aid in finding this

15 ~~line~~ ~~chains~~ distant.


**M. 6. B.**

from which this Corner bears

side of tree

tree 6 inches diameter, on the S.W.

Metal Location Poster is on a **Aspen**



(Make sketch of topography near Corner)

T. 59N R. 26W 4th Mer.