

U. S. Department of Agriculture

FOREST SERVICE

H-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 7 P Mer.

50 1/16 Corner common to Sections 9, and

Corner consists of a (not) in place


State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

George F. ... (Signature)

(Signature)


7-35 (Date)

Const. Foreman S.M. (Title)

(Title)

Corner again.
 In 1/4 in. between of a dump
 of cedar south of large
 area No

Give any further facts which will aid in finding this
 0.05 chains distant.
 from which this Corner bears
 side of E
 tree 12 inches diameter, on the
 Metal Location Poster is on a Dead Cedar



(Make sketch of topography near Corner)

T. R. Mer.