

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST Posted: 1-12

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

E 1/16 Corner common to Sections
28, and 33

Corner consists of a 4" ASPEN (not) in place

State condition good (1" iron pipe 6")

Dimensions above ground 2' 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 28		S 33	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 28		S 33	
B.T		I.T	

Species W. pine W. pine

Diameter 7" 7"

Bearing N 35° W N 25° E

Distance 89 Li 1 chain

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. M. Muegler

(Signature)

Field ass't

(Title)

1-4-35

(Date)

LAND LEVEL SECOND
GROWN WITH ASPEN

Corner again.


Give any further facts which will aid in finding this

chain distant.

From which this Corner bears S 25° W

side of tree

Metal Location Poster is on a W.P.I.N.E tree 7 inches diameter, on the S.W.



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

V-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

E 1/16 Corner common to Sections
28, and 33

Corner consists of a 4" ASPEN (not) in place

State condition good (1" IRON PIPE 6")

Dimensions above ground 2' 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
28		33	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S		S	
28		33	
B.T.		B.T.	

Species W. PINE W. PINE
 Diameter 7" 7"
 Bearing N 35° W N 25° E
 Distance 89 li 1 chain no

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No

Emilia Meyer
(Signature)

1-4-35
(Date)


Field Ass't
(Title)

LAND level second
grows with a span
Corner again.

Give any further facts which will aid in finding this
chaine distant.

from which this Corner bears
S 25. W
side of tree

tree 7 inches diameter, on the
Metal Location Poster is on a
PINE S. W.



(Make sketch of topography near Corner)

T 59 N R 26 W 7 EA Mer.

U. S. Department of Agriculture
FOREST SERVICE

V-12

chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

E 1/4 Corner common to Sections
28, and 33

Corner consists of a 4" ASPEN (not) in place

State condition good (1" IRON PIPE 6")

Dimensions above ground 2' 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
28		33	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S		S	
28		33	
B.T		B.T	

Species W. PINE W. PINE

Diameter 7" 7"

Bearing N 35° W N 75° E

Distance 89 Li 1 chain

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Emin Meagher

(Signature)

Field ass't

(Title)

1-4-35

(Date)

LAND level section
BROWN & ASPEN

Corner again.

Give any further facts which will aid in finding this


chain assistant.

1
from which this Corner bears S 25° W

side of tree

tree: 7 inches diameter, on the S. W.

Metal Location Poster is on a W. PINE



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.