

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

T-13

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 26 W. 4th Mer.

V4 Corner common to Sections

, , 27, and 28

Corner consists of a 4" N. Pine post (not) in place

State condition good 1" Iron Pipe 6" high

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	28		27
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S		S
	28		27
	B.T.		B.T.

Species N. Pine N. Pine

Diameter 6" 6"

Bearing S 46° W N 34° E

Distance 25 LKS. 35 LKS.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

1-3-35 Field Ass't

(Date)

(Signature)

(Title)

VERY NICE STAND
OF SECOND GROWTH
N. Pine. land hill

Corner again.

Give any further facts which will aid in finding this


25-115 chains distant.

from which this Corner bears N. 46° E

side of tree

tree 6 inches diameter, on the N. E

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 47 E Mer.

U. S. Department of Agriculture
FOREST SERVICE

T-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T 59 N R. 26 W 4th Mer.

1/4 Corner common to Sections 27, and 28

Corner consists of a 4" N. pine post in place
State condition good 1" iron pipe 6" high

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	28		27
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S		S
	28		27
	B.T		B.T

Species N. pine N. pine

Diameter 6" 6"

Bearing S 46° W N 37° E

Distance 25 lks 35 lks

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Erwin Meagher

(Signature)

Field Ass't

(Title)

1-3-35
(Date)

VERY NICE STAND
OF SECOND GROWTH
N. PINE LAND HILL

Corner again:

Give any further facts which will aid in finding this


25 1/2 miles distant.

From which this Corner bears N 46. E

side of tree

tree 6 inches diameter, on the N. E.

Metal Location Poster is on a N. PINE



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 7th Mer.