

U. S. Department of Agriculture

FOREST SERVICE

C-14

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

WC 116

Corner common to Sections

Corner consists of a Cedar post (not) in place

State condition

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Cardinal position diagram with four empty boxes for N, W, S, E.

N W S E

Diagonal position diagram with four empty boxes for NW, SW, SE, NE.

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Two rows of four empty boxes for sketching bearing trees and rocks.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S

Signature of George W. Jennings

(Signature)

11-22-35

(Date)

Signature of J. H. ...

(Title)

Dotted lines for notes.

*On slope towards Survey*

Corner again.

Give any further facts which will aid in finding this

chains distant. *0.06*


from which this Corner bears *WEST*

side of *tree*

tree *3* inches diameter, on the

*SE*

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)