

U. S. Department of Agriculture

FOREST SERVICE

C-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

1/4 Corner common to Sections

2, and 3

Corner consists of a Cedar stake in place

State condition

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? U. S. F. S.

George D. Jennings  
(Signature)

11-21-35  
(Date)

Jr. Foreman  
(Title)

E. side of picket line  
About 2 cns. 50' swamp

Corner again.

Give any further facts which will aid in finding this


0.16 chains distant.

From which this Corner bears 360 E

side of tree

tree 3 inches diameter, on the SE

Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T. 59 R. 26 Mer. 4