

U. S. Department of Agriculture  
FOREST SERVICE

B-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.  
N 1/16 Corner common to Sections

\_\_\_\_\_, 2, and 3

Corner consists of a Cedar stake (not) in place  
State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? X

If not, why? U.S.F.S.

George J. Jennings  
(Signature)

11-21-35  
(Date)

J. J. Sherman C&M  
(Title)


-----  
-----  
-----  
-----  
-----

Corner again.  
On edge of 76 Swamp.  
Poster is on first line

Give any further facts which will aid in finding this  
chains distant.

0.28  
From which this Corner bears  
side of *tree*

tree 12 inches diameter, on the *East*  
Metal Location Poster is on a *W. Corner*



(Make sketch of topography near Corner)