

U. S. Department of Agriculture
FOREST SERVICE

J-18

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

W/16 Corner common to Sections
11, and 14

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S.

(Signature)

12-3-35


(Date)

(Title)

Corner again.
 In "In Swamp 5 of Twp 511
 line 1/2 ch.

Give any further facts which will aid in finding this
 chains distant.

0.12
 From which this Corner bears
 side of tree 4 inches diameter, on the
 Metal Location Poster is on a B. Spruce
 538W



(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture

FOREST SERVICE

Posted J-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th Mer.

W 1/16 Corner common to Sections

11, and 14

Corner consists of a Wood Post & Iron Rod (not) in place

State condition Good

Dimensions above ground 42 x 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W 1/16		W 1/16					
S 11		S 14					
N	W	S	E	NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W 1/16	W 1/16		
S 11	S 14		
BT	BT		

Species B. SP. B. SP.


Diameter 4.5" 6.0"

Bearing N 1/2 W S 87 E


Distance 20ch 41ch

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____


 (Signature)


12/19/34
 (Date)


 (Title)

.....
.....
.....
.....
.....

Corner again.
Located in lowland type
of cover - Black willow
Hs Per

Give any further facts which will aid in finding this
33 chains distant.
from which this Corner bears S 4° E
side of tree.
tree 2.2 inches diameter, on the west
Metal Location Poster is on a Hs Per



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

J-18

CHIPPEWIC NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W Mer. 4th

W 1/16 Corner common to Sections
11, and 14

Corner consists of a Wood post + Iron rod (not) in place
State condition Good

Dimensions above ground 42 + 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W 1/16		W 1/16	
S 11		S 14	

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W 1/16	W 1/16		
S 11	S 14		
BT	BT		

Species B. SP. B. SP.

Diameter 4.5 4.5"

Bearing N 1/2° W S 87° E

Distance .20 ch .41 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

[Signature]

(Signature)

(Date)

(Title)


Corner again.
located in
Corner - Bl. Spruce, copper
+ located within boundary

Give any further facts which will aid in finding this
chains distant.

from which this Corner bears $S 40^{\circ} E$

side of Tree
tree .72 inches diameter, on the West

Metal Location Poster is on a $H 5 F 7$



(Make sketch of topography near Corner)

T 39 N R 26 W 4 T A Mer.

U. S. Department of Agriculture
FOREST SERVICE

5-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

W $\frac{1}{16}$ Corner common to Sections.....,,, and 14.....
Corner consists of a wood Post + Iron Rod (not) in place

State condition Good

Dimensions above ground 42 + 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

W $\frac{1}{16}$		W $\frac{1}{16}$	
S 11		S 14	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W $\frac{1}{16}$	W $\frac{1}{16}$		
S 11	S 14		
BT	BT.		

Species B. Sp. B. Sp.

Diameter 4.5" 6.0"

Bearing N $\frac{1}{2}$ ° W S 87° E

Distance 20 ch 41 ch

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

12/19/34
(Date)


Edward J. Culkrasik
(Signature)

Rich. Foreman
(Title)

.....
.....
.....
.....
.....

located in Howland Type
of cover - Bl Spruce Aspen
Hider + willow
Corner again.

Give any further facts which will aid in finding this
..... chains distant.
..... 33
from which this Corner bears S 4° E
side of T.R.S.
tree 7.2 inches diameter, on the west
Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T 59 N R 26 W 4th Mer.