

U. S. Department of Agriculture  
FOREST SERVICE

M-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

5 1/16

Corner common to Sections

13, and 14

Corner consists of a N. Pine stake (not) in place

State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S

George H. Jennings  
(Signature)

9-27-28

(Date)


J. H. ...  
(Title)

Blank lined area for notes at the top of the page.

Corner again.  
In small N.R. stand SE of Muskego chain in dia.

Give any further facts which will aid in finding this chains distant.

0.02 from which this Corner bears SE side of tree 8 inches diameter, on the SE Metal Location Poster is on a Nor. Pinc.



(Make sketch of topography near Corner)

T. 59N R. 26W 474D Mer.